



Fire resistance test report

Test standard: Sections 2 and 10 of AS 1530.4:2014

Test sponsor: H B Fuller Aus Co P/L; USG Boral

Job number: 48763900

Test date: 31 May 2017 Revision: R1.1

Warringtonfire: accredited for compliance with ISO/IEC 17025 - Testing











Quality management

Revision	Date	Information about the report			
R1.0	26 July	Description	Initial issue		
	2017		Prepared by		Reviewed by
		Name	Patrick Chan		Steven Halliday
R1.1	3	Description	Amendment on the thickness of the separating element		element
	December 2021		Prepared by	Reviewed by	Authorised by
		Name	Mohammed Taher	Patrick Chan	Mandeep Kamal
		Signature	Holest	Patil Cham	Takamel.







Executive summary

This report documents the findings of the fire resistance test of penetration systems in accordance with sections 2 and 10 of AS 1530.4:2014. The testing was done on 31 May 2017.

Warringtonfire performed the test at the request of H B Fuller Aus Co P/L and USG Boral.

Table 1 provides details of the test assembly, and Table 2 provides a summary of the test specimen. A summary of the results is provided in Table 3.

Table 1 Test assembly

Item	Detail		
Separating element	Boral Firestop 13mm Plasterboard wall system		
Nominal separating element size	Width	1600 mm	
	Height	1600 mm	
	Thickness	116 mm	
Number of penetration systems	Six		
Restraint conditions	Restrained on all edges		

Table 2 Test specimen

Penetration system / control joint	Service	Local fire-stopping protection	Local aperture size (mm)
А	2 x TPS cables	2 layers of 13mm Firestop plasterboard HB Fuller Firesound sealant	Ø20 mm
В	NB 25 mm Galvanised steel pipe	2 layers of 13mm Firestop plasterboard HB Fuller Firesound sealant	Ø40 mm
С	NB 32 mm Galvanised steel pipe	HB Fuller Firesound sealant 50mm × 50mm fillet cone	Ø50 mm
D	5 x TPS cables	HB Fuller Firesound sealant 50mm × 50mm fillet cone	Ø25 mm
Е	Group A configuration cable tray	HB Fuller Firesound sealant 70mm × 50mm fillet cone	335 mm wide × 70 mm long
F	Group B configuration cable tray	HB Fuller Firesound sealant 70mm × 50mm fillet cone	181 mm wide x 130 mm long

Test standard: Sections 2 and 10 of AS 1530.4:2014 Job number: 48763900







Table 3 Test results

Table 3 Test results				
Penetration system/ control joint	Criteria	Results	Fire resistance level (FRL)	
А	Structural adequacy	Not applicable	-/180/180	
	Integrity	No failure at 180 minutes		
	Insulation	No failure at 180 minutes		
В	Structural adequacy	Not applicable	-/180/180	
	Integrity	No failure at 180 minutes		
	Insulation	No failure at 180 minutes		
С	Structural adequacy	Not applicable	-/180/120	
	Integrity	No failure at 180 minutes		
	Insulation	Failure at 153 minutes		
D	Structural adequacy	Not applicable	-/180/120	
	Integrity	No failure at 180 minutes		
	Insulation	Failure at 125 minutes		
E	Structural adequacy	Not applicable	-/180/45	
	Integrity	No failure at 180 minutes		
	Insulation	Failure at 58 minutes		
F	Structural adequacy	Not applicable	-/180/120	
	Integrity	No failure at 180 minutes		
	Insulation	Failure at 122 minutes		







Contents

1.	Introduct	6	
2.	Test spec	cimen	6
2.1 2.2	Schedule o	of components a details	6 11
3.	Test prod	cedure	12
4.	Test mea	asurements and results	13
5.	Application	on of test results	14
5.1 5.2 5.3	Test limitati Variations f Uncertainty	14 14 14	
Арре	endix A	Drawings of test assembly	15
Арре	endix B	Test observations	20
Арре	endix C	Direct field of application	23
Арре	endix D	Instrumentation locations	25
Арре	endix E	Test data	30
Appe	endix F	Photographs	40







1. Introduction

This report documents the findings of the fire resistance test of penetration systems in accordance with sections 2 and 10 of AS 1530.4:2014. The testing was done on 31 May 2017.

Warringtonfire performed the test at the request of the test sponsor listed in Table 4.

Table 4 Test sponsor details

Test sponsor	Address
H B Fuller Aus Co P/L	16-22 Redgum Dr Dandenong South VIC 3175
LICC Porel	Australia
USG Boral	251 Salmon Street Port Melbourne VIC 3207
	Australia

2. Test specimen

2.1 Schedule of components

Table 5 describes the test specimen and lists the schedule of components. These were provided by the test sponsor and surveyed by Warringtonfire.

All measurements were done by Warringtonfire – unless indicated otherwise.

Detailed drawings of the test specimen are provided in Appendix A.

 Table 5
 Schedule of components

Item	Description				
Separat	eparating element (SE)				
1.	Item name	Plasterboard wall			
	Product name	Boral Firestop	13 mm Plasterboard wall system		
	Density	894 kg/m³ (mea	asured)		
2.	Item name	Steel frame			
	Product name	0	do steel stud do steel track		
	Size	Rondo steel stud	64 mm web × 33.5 mm flange × 0.55 mm BMT		
		Rondo steel track	64°mm web × 29 mm flange × 0.5 mm BMT		
SE	Overall size	1600 mm wide × 1600 mm long × 116 mm thick			
	Restraint conditions	Restrained on all four edges			
	Installation	The wall incorporated wall incorporated two layers of 13 mm thick plasterboard on both exposed and unexposed sides with 64 mm Rondo steel frame.			
		The perimeter tracks and studs were secured to the concrete blockwork with 6 mm masonry anchors at 600 mm centres.			
		The wall was divided into six 800 mm wide x 463 mm height compartments.			
		The compartments were separated from each other by 13 mm thick plasterboard with stone wool inserted into the cavity of the steel stud and nogging.			
	Compartmentatio n	A Extra two layers of 13 mm Firestop plasterboard were applie on the wall system as an extra protection system of the pipe on both the exposed and unexposed sides.			

Test standard: Sections 2 and 10 of AS 1530.4:2014

Job number: 48763900







Item	Description		
			A rectangle hole which extended from the top edge of the wall system to the core hole was formed on the wall system to allow the bundle of cable inserted through the wall system. The protection board was 150 mm height × 550 mm wide and secured to the wall with 8-off S type screws.
			Part of the bottom of the protection plasterboard was cut out to allow the protection board to be installed through the bundle of cable.
		В	Extra two layers of 13 mm Firestop plasterboards were applied on the wall system as an extra protection of the pipe on both exposed and unexposed side.
			A rectangle hole which extended from the top edge of the wall system to the core hole was formed on the wall system to allow the bundle of cable inserted through the wall system.
			The protection board was 150 mm height × 550 mm wide and secured to the wall with 8-off S type screws.
			Part of the bottom of the protection plasterboard was cut out to allow the protection board to be installed through the pipe.
		С	No extra feature installed in the wall system
		D	No extra feature installed in the wall system
		Е	No extra feature installed in the wall system
		F	No extra feature installed in the wall system
Fire-sto	ppping protections		
Sealant	t		
3.	Item name	Sealant	
	Product name	H. B. Fuller Fi	resound sealant
	Density	1496 kg/m³	
Service	es .		
4.	Item name	NB 25 mm ga	vanised steel pipe
	Material	Galvanised ste	eel
	Size	Outer diameter	Ø33.7 mm
		Wall thickness	3.1 mm
5.	Item name	NB 32 mm Ga	Ivanised steel pipe
	Material	Galvanised sto	eel
	Size	Outer diameter	Ø42.4 mm
		Wall thickness	3.2 mm
6.	Item name TPS cables		
	Manufacturer	Prysmian	
	Product name	2.5 mm² 2C+E TPS cable	
	Size	Width	12.2 mm
		Length	5.5 mm







Item	Description				
		Cross section	2.5 mm ² each core		
		area			
7.	Item name	D1 power cable group			
	Product name	CMI Electric	cal product 0.6/1kV × 90 1	C630SQmm CU 2013	
				-90 3C × 185 mm ² + E 70 mm ²	
		Advance cable 2017 V90 Electrical cable 450/750V 6 mm² 3C+E			
		 WW VIPERCON electric cable 3C + E 16 XLPE / PVC 5V90 AS/NZS 5000.1 0.6/1kV 2019 1016 UA 			
	Size	Cable cross se	ction area	Outer diameter	
		630 mm²		41 mm	
		185 mm²		52 mm	
		6 mm²		13 mm	
		16 mm²		18 mm	
	Number of cables	• 1 × 630 mm	n² cable		
		• 1 × 185 mm	n² cable		
		• 3 × 6 mm ² (
		• 8 × 16 mm ²			
8.	Item name	300 mm cable			
	Product name	Burndy® LT3-300-3 ladder-tray			
	Size	Width		325 mm	
		Height		47.0 mm	
		Thickness		1.0 mm	
	Material	Galvanised ste	el		
9.	Item name	D2 communication cable group			
	Product name	Prysmian DW Maxtel CAT 3 50 PR internal telephone 0.5 mm T50P I J/N 65048/C			
	Manufacturer	Prysmian			
	Size	18 mm × 11 mm			
	Number of cables	60 x CAT 3 cat	oles		
10.	Item name	150 mm cable	tray		
	Product name	Burndy® LT3-1	50-3 ladder tray		
	Size	Width		175 mm	
		Height		50 mm	
		Thickness 1.0 mm		1.0 mm	
Fixings					
11.	Item name	Screws			
	Product description	S type screws			
Penetra	ition system A				
Α	Service	Bundle of TPS	cable (2-off cable)		







Item	Description				
	Service detail	The service was installed 60mm away from the top edge of the compartment. The service protruded 500 mm from the exposed and unexposed sides of the separating element.			
	Service support	The service was supported at 200 mm and 450 mm away from the wall system with plastic cable ties on the threaded rods.			
	Aperture size	Ø20 mm			
	Main fire-stopping	protection system			
	Protection	The service was protected by extra two layers of 550 mm × 150 mm × 13 mm plasterboard (item 1) on the exposed and unexposed side. The plasterboards were located 20 mm below the top edge of the wall system.			
	Local fire-stopping	protection			
	Protection	The sealant (Item 2) was applied:			
		 On the interface between the galvanize pipe and the plasterboard on the exposed and unexposed side. 			
		On the 20mm gap between the protection plasterboard and the concrete lintel			
		In the cut out of the wall system and the protection plasterboard board.			
Penetra	tion system B				
В	Service	NB 25 mm galvanize pipe (Item 3).			
	Service detail	The service was installed 70mm away from the top edge of the compartment. The service protruded 500 mm from the exposed and unexposed side of the separating element.			
	Service support	The service was supported at 200mm and 450mm away from the separating element with pipe clamp.			
	Aperture size	Ø40 mm			
	Local fire-stopping protection				
	Protection	The service was protected by extra two layers of 550 mm × 150 mm × 13 mm plasterboard (Item 1) on the exposed and unexposed side. The plasterboards were located 20 mm below the top edge of the wall system.			
	Local fire-stopping protection				
	Protection	The sealant (Item 2) was applied:			
		On the interface between the galvanize pipe and the plasterboard on the exposed and unexposed side.			
		On the 20 mm gap between the protection plasterboard and the concrete lintel			
		In the cut out of the wall system and the protection plasterboard board.			
Penetra	tion system C				
С	Service	NB 32 mm Galvanised steel pipe. (item 5)			
	Service detail	The service was installed 480 mm away from the west edge of the wall system and 735 mm from the sill. The service protruded 500 mm away from both the exposed and unexposed sides of the separating element and capped with wielded steel plate on the exposed side.			
	Service support	The service was supported at 200mm and 450mm away from the separating element with pipe clamps.			
	Aperture size	Ø50 mm			







Item	Description				
	Protection	The sealant (item 3) was applied on the annular gap between the separating element and the service and finished with 50 mm x 50 mm fillet cone on both exposed and unexposed sides.			
Penetra	ation system D				
D	Service	2 × bundle of cable (5 × TPS cables) (item 6).			
	Service detail	The Ø50 mm core hole was located 1020 mm away from the west edge of the wall system and Ø25 mm core hole was located 1265 mm away from the west edge. Both holes were 735 mm above the sill.			
		The service protruded 500 mm away from both the exposed and unexposed sides of the separating element.			
	Service support	The service was supported at 200 mm and 450 mm away from the separating element with cable ties on the threaded rods.			
	Aperture size	West: Ø50 mm East: Ø25 mm			
	Local fire-stopping	protection			
	Protection	A bundle of cable was inserted into each core holes. Sealant (item 3) was applied in the annual gap and finished with a 50 mm × 50 mm fillet cone on both the exposed and unexposed sides.			
Penetra	ation system E				
Е	Service	D1 power cable group (item 7) with 300 mm cable tray			
	Service detail	The service was installed at 300 mm away from the west edge of the wall system and 190 mm away from the sill.			
		The service protruded 500 mm from both the exposed and unexposed sides.			
	Service support	The service was supported at 200 mm and 450 mm away from the separating element on the Unistruts.			
	Aperture size	335 mm wide x 70 mm long			
	Local fire-stopping protection				
	Protection	Sealant (item 3) was applied into the spacing between the separating element and the service and finished off with a fillet cone on both the exposed and unexposed sides. The fillet cone was 70 mm × 50 mm on the top section of the cone and 50 mm × 50 mm on the bottom section.			
Penetra	ation system F				
F	Service	D2 communication cable group (item 9) with 150 mm cable tray (item 10)			
	Service detail	The service was installed at 1035 mm away from the west edge of the wall system and 190 mm away from the sill.			
		The service protruded 500 mm from both the exposed and unexposed side of the separating element.			
	Service support	The service was supported at 200 mm and 450 mm away from the separating element on the Unistruts.			
	Aperture size	181 mm wide x 130 mm long			
	Local fire-stopping	protection			
	Protection	Sealant (item 3) was applied into the spacing between the separating element and the service and finished off with a fillet cone on both the exposed and unexposed sides. The fillet cone was 70 mm \times 50 mm on the top section of the cone and 50 mm \times 50 mm on the bottom section.			
	1	I .			







2.2 Installation details

Table 6 lists the installation details for the test specimen.

Table 6 Installation details

Item	Detail
Start date for construction of separating element	17 May 2017
Start date for installation of fire-stopping protection for the penetration systems	21 May 2017
Completion date for constructing and installing the test specimen	18 May 2017
Separating element constructed by	Representatives of Warringtonfire
Fire-stopping protection for penetration systems installed by	Representatives of the test sponsor
Symmetry	Symmetrical







3. Test procedure

Table 7 details the test procedure for this fire resistance test.

Table 7 Test procedure

Item	Detail				
Statement of compliance	The test was performed in accordance with the requirements of sections 2 and 10 of AS 1530.4:2014 for penetration systems, subject to the variations below.				
Variations	The pressure for the 5–15-minute period was above the limits presc in AS1530.4-2014 by 8-39 Pa. This exceeded the pressure requirer the standard and was therefore more severe than required by the standard. Based on the above the results of this test remain valid.				
Pre-test conditioning	The construction and installation of th 18 May 2017. The test specimen was temperatures and conditions between test specimen and the start of the test	subjected to normal laboratory the completion of construction of the			
Sampling / specimen selection	for the fire resistance test. The results obtained during the test only apply to the test sample				
Ambient leberatory temperature	received and tested by Warringtonfire Start of the test	13 °C			
Ambient laboratory temperature		13 °C			
	Maximum temperature	19 °C			
Test duration	Maximum temperature 19 °C 180 minutes				
Instrumentation and equipment	The instrumentation was provided in accordance with AS 1530.4-2014 and as detailed below: The furnace temperature was measured by 4-off mineral insulated metal sheathed Type K thermocouples with wire diameters not greater than 1 mm and overall diameter of 3 mm with the measuring junction insulated from the sheath. The thermocouples protruded a minimum of				
	 25 mm from steel supporting tubes. The unexposed side specimen temperatures were measured by K thermocouples with wire diameters less than 0.5 mm diameter soldered to 12 mm diameter × 0.2 mm thick copper discs covered 30 mm × 30 mm × 2.0 mm inorganic insulating pads. The thermocouples positions are described in Table 10 and are show Figure 6 in Appendix D. A roving thermocouple was available to measure temperatures a positions that appeared hotter than the positions monitored by the thermocouples. Cotton pads were available during the test to assess the perform under the criteria for integrity. 				

Test standard: Sections 2 and 10 of AS 1530.4:2014 Job number: 48763900







4. Test measurements and results

Table 8 summarises the results the specimen achieved against the performance criteria listed in sections 2 and 10 of AS 1530.4:2014, subject to the variations listed in section 3.

Appendix E includes details of the measurements taken during the test.

Table 9 in Appendix B includes observations of any significant behaviour of the specimen and details of the occurrence of the various performance criteria specified in AS 1530.4:2014.

Photographs of the specimen are included in Appendix F.

Table 8 Test results

Penetration system/ control joint	Criteria	Results	Fire resistance level (FRL)			
А	Structural adequacy	Not applicable	-/180/180			
	Integrity	No failure at 180 minutes				
	Insulation	No failure at 180 minutes				
В	Structural adequacy	Not applicable	-/180/180			
	Integrity	No failure at 180 minutes				
	Insulation	No failure at 180 minutes				
С	Structural adequacy	Not applicable	-/180/120			
	Integrity	No failure at 180 minutes				
	Insulation	Failure at 153 minutes				
D	Structural adequacy	Not applicable	-/180/120			
	Integrity	No failure at 180 minutes				
	Insulation	Failure at 125 minutes				
Е	Structural adequacy	tural adequacy Not applicable				
	Integrity	No failure at 180 minutes				
	Insulation	Failure at 58 minutes				
F	Structural adequacy	Not applicable	-/180/120			
	Integrity	No failure at 180 minutes				
	Insulation	Failure at 122 minutes				







5. Application of test results

5.1 Test limitations

The results of this fire test may be used to directly assess fire hazard, but it should be recognized that a single test method will not provide a full assessment of fire hazard under all fire conditions. The results only relate to the behaviour of the specimen of the element of the construction under the conditions of the test; they are not intended to be the sole criteria for assessing the potential fire performance of the element in use nor do they necessarily reflect the actual behaviour in fires.

5.2 Variations from the tested specimen

This report details methods of construction, the test conditions and the results obtained when the specific element of construction described herein was tested in accordance with the test method with AS1530.4. Any significant variation with respect to size, constructional details, loads, stresses, edge or end conditions, other than those allowed under the field of direct application in the relevant test method, is not addressed by this report. It is recommended that any proposed variation to the tested configuration other than as permitted under the field of direct application specified in Appendix C should be referred to the test sponsor in the first instance to obtain appropriate documentary evidence of compliance from Warringtonfire or another accredited testing authority.

5.3 Uncertainty of measurements

Because of the nature of fire resistance testing and the consequent difficulty in quantifying the uncertainty of measurement of fire resistance, it is not possible to provide a stated degree of accuracy for the result.

Test standard: Sections 2 and 10 of AS 1530.4:2014 Job number: 48763900







Appendix A Drawings of test assembly




Figure 1 Elevation view of test specimen (unexposed side)








Figure 2 Elevation view of test specimen (exposed side)








Figure 3 Cross section A-A








Figure 4 **Cross section B-B**

Test standard: Sections 2 and 10 of AS 1530.4:2014 Job number: 48763900








Figure 5 Cross section C-C







Appendix B Test observations

Table 9 shows the observations of any significant behaviour of the specimen during the test.

Table 9 Test observations

		l'est observations					
Ti	me	Observation					
Min	Sec						
Penet	ration	system A					
00	00	Fire resistance test commenced, and the ambient temperature was approximately 13°C.					
30	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014.					
60	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014.					
90	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014.					
111	00	The sealant cone had expanded.					
120	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014.					
180	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014.					
180	00	Test stopped at the request of the sponsor					
Penet	ration	system B					
00	00	Fire resistance test commenced, and the ambient temperature was approximately 13°C.					
30	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014.					
60	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014.					
80	44	The sealant cone had expanded					
90	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014.					
120	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014.					
180	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014.					
180	00	Test stopped at the request of the sponsor					
Penet	ration	system C					
00	00	Fire resistance test commenced, and the ambient temperature was approximately 13°C.					
30	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014.					
42	18	Part of the sealant cone had liquefied and dripping to the specimen F					
60	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014.					
72	30	The sealant cone had expanded					
90	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014.					
	_						

Test standard: Sections 2 and 10 of AS 1530.4:2014

Job number: 48763900







Min Sec 120 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014 153 50 TC 031 on the metal pipe, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 cleause 2.13.3(b), where the maximum temperature of Thermocouple TC 031 exceeded the initial temperature by more than 180°C. 180 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014. 180 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 60 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 72 30 The sealant cone had expanded 90 01 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 120 02 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 125 15 TC 051 on the bundle of TPS cable on the east side hole, 25mm away from sealant recorded a temperature of 193°C. 137 40 TC 041 on the bundle of TPS cable on the west side hole, 25mm away from sealant recorded a temperature of 193°C. 148 0 TC 041 on the bundle of TPS cable on the west side hole, 2	Time		Observation					
AS 1530.4-2014 153 50 TC 031 on the metal pipe, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 031 exceeded the initial temperature by more than 180°C. 180 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014. 180 00 Fire resistance test commenced, and the ambient temperature was approximately 13°C. 30 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 180 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 180 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 180 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 180 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 180 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 181 TC 051 on the bundle of TPS cable on the east side hole, 25mm away from sealant recorded a temperature of 193°C. 180 Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 051 exceeded the initial temperature by more than 180°C. 180 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014. 180 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014. 180 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014. 180 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014. 180 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 180 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 181 Part of the sealant cone had liquefied, and bu	Min	Sec						
Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 031 exceeded the initial temperature by more than 180°C. 180 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014. 180 00 Test stopped at the request of the sponsor. Penetration system D 00 00 Fire resistance test commenced, and the ambient temperature was approximately 13°C. 30 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 60 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 72 30 The sealant cone had expanded 90 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 120 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 121 15 TC 051 on the bundle of TPS cable on the east side hole, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014. 180 00 Fire resistance test commenced, and the ambient temperature was approximately 13°C. 180 00 Fire resistance test commenced, and the ambient temperature was	120	00						
Penetration system D 00 00 Fire resistance test commenced, and the ambient temperature was approximately 13°C. 30 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 60 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 72 30 The sealant cone had expanded 90 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 120 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 125 15 TC 051 on the bundle of TPS cable on the east side hole, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 051 exceeded the initial temperature by more than 180°C. 137 40 TC 041 on the bundle of TPS cable on the west side hole, 25mm away from sealant recorded a temperature of Thermocouple TC 051 exceeded the initial temperature by more than 180°C. 138 00 To 041 on the bundle of TPS cable on the west side hole, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of the sponsor. Penetration system E 00 00 Fire resistance test commenced, and the ambient temperature was approximately 13°C. 180 00 Test stopped at the request of the sponsor. Penetration system E 180 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 180 180 Amount of smoke emission had increased. 30 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 319 Part of the sealant cone had liquefied, and bubbling appeared. 320 Tot 4 on the 630mm2 single core cable, 25mm away from sealant recorded a temperature of 193°C. Failure of insu	153	50	Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 031 exceeded the initial temperature by					
Penetration system D 00 00 Fire resistance test commenced, and the ambient temperature was approximately 13°C. 30 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 60 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 72 30 The sealant cone had expanded 90 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 120 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 125 15 TC 051 on the bundle of TPS cable on the east side hole, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 051 exceeded the initial temperature by more than 180°C. 137 40 TC 041 on the bundle of TPS cable on the west side hole, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 041 exceeded the initial temperature by more than 180°C. 180 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014. 180 00 Test stopped at the request of the sponsor. Penetration system E 00 00 Fire resistance test commenced, and the ambient temperature was approximately 13°C. 190 Smoke emission appeared from the cable tray gap 24 30 Amount of smoke emission had increased. 30 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 28 18 Part of the sealant cone had liquefied, and bubbling appeared. 75 TC 104 on the 630mm2 single core cable, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of 193°C. Fail	180	00	The specimen had continued to maintain integrity in accordance with AS 1530.4-2014.					
00 00 Fire resistance test commenced, and the ambient temperature was approximately 13°C.	180	00	Test stopped at the request of the sponsor.					
00 00 Fire resistance test commenced, and the ambient temperature was approximately 13°C.								
The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014.	Penet	ration s	ystem D					
AS 1530.4-2014. The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. The sealant cone had expanded The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. To 01 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. To 01 on the bundle of TPS cable on the east side hole, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 051 exceeded the initial temperature by more than 180°C. To 041 on the bundle of TPS cable on the west side hole, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 041 exceeded the initial temperature by more than 180°C. The specimen had continued to maintain integrity in accordance with AS 1530.4-2014. Test stopped at the request of the sponsor. Penetration system E On The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. To 104 on the 630mm2 single core cable, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 104 exceeded the initial temperature by more than 180°C.	00	00	Fire resistance test commenced, and the ambient temperature was approximately 13°C.					
AS 1530.4-2014. The sealant cone had expanded The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 041 exceeded the initial temperature by more than 180°C. The specimen had continued to maintain integrity in accordance with AS 1530.4-2014. Test stopped at the request of the sponsor. Penetration system E O	30	00						
90 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 120 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. 125 15 TC 051 on the bundle of TPS cable on the east side hole, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 051 exceeded the initial temperature by more than 180°C. 137 40 TC 041 on the bundle of TPS cable on the west side hole, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 041 exceeded the initial temperature by more than 180°C. 180 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014. 180 00 Test stopped at the request of the sponsor. Penetration system E 00 00 Fire resistance test commenced, and the ambient temperature was approximately 13°C. 190 Smoke emission appeared from the cable tray gap 24 30 Amount of smoke emission had increased. 30 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014 28 18 Part of the sealant cone had liquefied, and bubbling appeared. TC 104 on the 630mm2 single core cable, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 104 exceeded the initial temperature by more than 180°C.	60	00						
AS 1530.4-2014. The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014. To 051 on the bundle of TPS cable on the east side hole, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 051 exceeded the initial temperature by more than 180°C. To 041 on the bundle of TPS cable on the west side hole, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 041 exceeded the initial temperature by more than 180°C. The specimen had continued to maintain integrity in accordance with AS 1530.4-2014. Test stopped at the request of the sponsor. Penetration system E O	72	30	The sealant cone had expanded					
AS 1530.4-2014. 125 15 TC 051 on the bundle of TPS cable on the east side hole, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 051 exceeded the initial temperature by more than 180°C. 137 40 TC 041 on the bundle of TPS cable on the west side hole, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 041 exceeded the initial temperature by more than 180°C. 180 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014. 180 00 Test stopped at the request of the sponsor. Penetration system E 00 00 Fire resistance test commenced, and the ambient temperature was approximately 13°C. 01 00 Smoke emission appeared from the cable tray gap 24 30 Amount of smoke emission had increased. 30 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014 48 18 Part of the sealant cone had liquefied, and bubbling appeared. 55 TC 104 on the 630mm2 single core cable, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 104 exceeded the initial temperature by more than 180°C.	90	00						
recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 051 exceeded the initial temperature by more than 180°C. 137 40 TC 041 on the bundle of TPS cable on the west side hole, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 041 exceeded the initial temperature by more than 180°C. 180 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014. 180 00 Test stopped at the request of the sponsor. Penetration system E 00 00 Fire resistance test commenced, and the ambient temperature was approximately 13°C. 01 00 Smoke emission appeared from the cable tray gap 24 30 Amount of smoke emission had increased. 30 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014 48 18 Part of the sealant cone had liquefied, and bubbling appeared. TC 104 on the 630mm2 single core cable, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 104 exceeded the initial temperature by more than 180°C.	120	00						
recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 041 exceeded the initial temperature by more than 180°C. 180 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014. 180 00 Test stopped at the request of the sponsor. Penetration system E 00 00 Fire resistance test commenced, and the ambient temperature was approximately 13°C. 01 00 Smoke emission appeared from the cable tray gap 24 30 Amount of smoke emission had increased. 30 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014 48 18 Part of the sealant cone had liquefied, and bubbling appeared. 55 TC 104 on the 630mm2 single core cable, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 104 exceeded the initial temperature by more than 180°C. 60 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014.	125	15	recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 051 exceeded the initial temperature by					
Penetration system E 00 00 Fire resistance test commenced, and the ambient temperature was approximately 13°C. 01 00 Smoke emission appeared from the cable tray gap 24 30 Amount of smoke emission had increased. 30 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014 48 18 Part of the sealant cone had liquefied, and bubbling appeared. TC 104 on the 630mm2 single core cable, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 104 exceeded the initial temperature by more than 180°C. 60 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014.	137	40	recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 041 exceeded the initial temperature by					
Penetration system E 00 00 Fire resistance test commenced, and the ambient temperature was approximately 13°C. 01 00 Smoke emission appeared from the cable tray gap 24 30 Amount of smoke emission had increased. 30 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014 48 18 Part of the sealant cone had liquefied, and bubbling appeared. 58 55 TC 104 on the 630mm2 single core cable, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 104 exceeded the initial temperature by more than 180°C. 60 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014.	180	00	The specimen had continued to maintain integrity in accordance with AS 1530.4-2014.					
00 Fire resistance test commenced, and the ambient temperature was approximately 13°C. 01 00 Smoke emission appeared from the cable tray gap 24 30 Amount of smoke emission had increased. 30 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014 48 18 Part of the sealant cone had liquefied, and bubbling appeared. 58 55 TC 104 on the 630mm2 single core cable, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 104 exceeded the initial temperature by more than 180°C. 60 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014.	180	00	Test stopped at the request of the sponsor.					
00 Fire resistance test commenced, and the ambient temperature was approximately 13°C. 01 00 Smoke emission appeared from the cable tray gap 24 30 Amount of smoke emission had increased. 30 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014 48 18 Part of the sealant cone had liquefied, and bubbling appeared. 58 55 TC 104 on the 630mm2 single core cable, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 104 exceeded the initial temperature by more than 180°C. 60 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014.								
01 00 Smoke emission appeared from the cable tray gap 24 30 Amount of smoke emission had increased. 30 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014 48 18 Part of the sealant cone had liquefied, and bubbling appeared. 58 55 TC 104 on the 630mm2 single core cable, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 104 exceeded the initial temperature by more than 180°C. 60 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014.	Penet	ration s	ystem E					
24 30 Amount of smoke emission had increased. 30 00 The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014 48 18 Part of the sealant cone had liquefied, and bubbling appeared. 58 55 TC 104 on the 630mm2 single core cable, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 104 exceeded the initial temperature by more than 180°C. 60 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014.	00	00	Fire resistance test commenced, and the ambient temperature was approximately 13°C.					
The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014 Part of the sealant cone had liquefied, and bubbling appeared. TC 104 on the 630mm2 single core cable, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 104 exceeded the initial temperature by more than 180°C. The specimen had continued to maintain integrity in accordance with AS 1530.4-2014.	01	00	Smoke emission appeared from the cable tray gap					
AS 1530.4-2014 18 Part of the sealant cone had liquefied, and bubbling appeared. 58 TC 104 on the 630mm2 single core cable, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 104 exceeded the initial temperature by more than 180°C. 60 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014.	24	30	Amount of smoke emission had increased.					
58 TC 104 on the 630mm2 single core cable, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 104 exceeded the initial temperature by more than 180°C. 60 00 The specimen had continued to maintain integrity in accordance with AS 1530.4-2014.	30	00						
temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 104 exceeded the initial temperature by more than 180°C. The specimen had continued to maintain integrity in accordance with AS 1530.4-2014.	48	18	Part of the sealant cone had liquefied, and bubbling appeared.					
	58	55	temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 104 exceeded the initial temperature by					
72 30 The sealant cone had expanded	60	00	The specimen had continued to maintain integrity in accordance with AS 1530.4-2014.					
	72	30	The sealant cone had expanded					







Time		Observation					
Min	Sec						
80	44	Smoke emission on the 185mm2 cable had increased. Discolouration appeared on the 16mm2 cables					
82	45	The sheath of the 185mm2 and 630mm2 cable had melted					
90	00	The specimen had continued to maintain integrity in accordance with AS 1530.4-2014					
120	00	The specimen had continued to maintain integrity in accordance with AS 1530.4-2014					
170	00	The molten sheath of the cables was dripping off from the cable tray.					
180	00	The specimen had continued to maintain integrity in accordance with AS 1530.4-2014					
180	00	Test stopped at the request of the sponsor.					
Penet	ration s	ystem F					
00	00	Fire resistance test commenced, and the ambient temperature was approximately 13°C.					
01	00	Smoke emission appeared from the cable tray gap					
24	30	Amount of smoke emission had increased.					
24	30	Discoloration appeared on the cables					
30	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014					
48	18	Part of the sealant cone had liquefied, and bubbling appeared.					
60	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014					
72	30	The sealant cone had expanded					
90	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014					
120	00	The specimen had continued to maintain integrity and insulation in accordance with AS 1530.4-2014					
122	75	TC 127 on the bottom of the cable tray, 25mm away from sealant recorded a temperature of 193°C. Failure of insulation in accordance with AS 1530.4-2014 clause 2.13.3(b), where the maximum temperature of Thermocouple TC 127 exceeded the initial temperature by more than 180°C.					
170	00	The molten sheath of the cables was dripping off from the cable tray.					
180	00	The specimen had continued to maintain integrity in accordance with AS 1530.4-2014					
180	00	Test stopped at the request of the sponsor.					







Appendix C Direct field of application

The text, figures and tables in this appendix have been taken from section 10 of AS 1530.4:2014.

C.1 General

The results of the fire test contained in the test report are directly applicable without reference to the testing authority to similar constructions where one or more of the changes set out in clauses 10.12.2 to 10.12.6 of AS 1530.4:2014 have been made.

C.2 Separating elements

- Results obtained from framed wall systems may be applied to the performance of a system in concrete, masonry or solid gypsum blocks of greater or equal thickness to that of the tested prototype. The reverse does not apply.
- Results obtained from framed wall systems may be applied to similar walls having studs of the same material with sizes greater than the tested prototype.
- Results obtained from a prototype test may be applied to framed wall systems of similar construction but having thicker facings of the same material applied to the stud.

C.3 Metal pipes

C.3.1 Sealing systems tested using standard configurations

The results may be applied to brass pipes of the same composition up to maximum outside diameter of 101.6 mm (normally 70/30 arsenical brass) and to copper and ferrous metal pipes having wall thicknesses greater than or equal to those listed in table 10.12.3.1 of AS 1530.4:2014, provided the same penetration sealing system was used for the above penetrations in the same type of separating element and all the specimens achieved the required FRL.

Note: For information on standard configurations, see Appendix F of AS 1530.4:2014.

TABLE 10.12.3.1
METAL PIPE DEEMED TO HAVE EQUIVALENT FIRE RESISTANCE LEVELS

Nominal size	Actual OD (outside diameter)	Actual wall thickness		
mm	mm	mm		
32	31.75	0.91		
40	38.10	0.91		
50	50.80	0.91		
65	63.50	0.91		
80	76.20	1.22		
90	88.90	1.22		
100	101.60	1.22		
125	127.00	1.42		
150	152.40	1.63		

C.3.2 Sealing systems tested not using standard configurations

Results obtained with a penetration sealing system protecting the opening around copper or brass pipes may be applied to pipes of the same material and to ferrous metal pipes having outside diameters not greater than the tested diameter, and wall thicknesses not less than the tested thickness.

Test standard: Sections 2 and 10 of AS 1530.4:2014

Job number: 48763900







Note: For information on standard configurations for metal pipes, see Appendix F of AS 1530.4:2014.

C.3.3 Shape and size of openings for penetration seals

For mineral-fibre, cast and gun-applied mastic seals, results obtained in openings with a smooth surface texture may be applied to openings having a rough surface texture.

C.3.4 Insulated – lagged – metal pipes

Where fire test data on the insulation system is not available, penetration sealing systems that have been subjected to the standard test with uninsulated metal pipes may be used, provided the appropriate requirements of clause 10.12.3.2 of AS 1530.4:2014 are satisfied and the following procedures are followed:

- If the insulation is non-combustible or is manufactured solely from mineral fibre, it shall be cut away where the service penetrates the separating element, and the opening shall be firestopped in accordance with the tested method.
- If the insulation is combustible, it shall be cut away for 1000 mm either side of the separating element (provided the pipe did not vent hot gases during the fire resistance test), and the pipe shall be fire-stopped in accordance with the tested method. A non-combustible lagging may be placed over the bare pipe. If venting occurs during the fire resistance test at a time less than the required FRL, a fire test shall be carried out to evaluate the insulated pipe system.

C.3.5 Alternative pipe materials

If an element is penetrated by —

- a pipe other than brass, copper or ferrous alloys
- a pipe of cross-section other than circular
- a pipe outside the field of application specified in this Standard for the standard test configuration, then the results obtained from a single tested system may be applied to these pipes provided the
 - melting point of the material is equal to or greater than the tested specimen
 - surface area to mass ratio of a cross-section of the pipe is equal to or less than the tested specimen
 - thermal conductivity is equal to or less than the tested specimen diffusivity of the material.

Test standard: Sections 2 and 10 of AS 1530.4:2014 Job number: 48763900


Revision: R1.1 Test sponsor: H B Fuller Aus Co P/L; USG Boral Page 24 of 42







Appendix D Instrumentation locations







Figure 6 Penetration system A

Figure 7 Penetration system B







Figure 8 Penetration system C

Figure 9 Penetration system D west









101 102 103 104

Figure 10 Penetration system D east

Figure 11 Penetration system D top



Figure 12 Penetration system E bottom




Figure 13 Penetration system F top










Figure 14 Penetration system F bottom







Table 10 Thermocouple locations

Table 10 Th	ermoco	uple locations
Penetration system	T/C #	Description
А	011	On the top of the bundle of TPS cables, 25mm away from the sealant
	012	On the side of the bundle of TPS cables, 25mm away from the sealant
	013	On the extra protection plasterboard, 25mm away from the sealant
	014	On the extra protection plasterboard, 25mm away from the sealant
	015	On the sealant in the extra protection plasterboard channel, 25mm away from the sealant fillet cone
	016	On the extra protection plasterboard, 25mm away from the wall system below the extra protection plasterboard channel.
	017	On the wall system, 25mm away from the extra protection plasterboard
	018	On the wall system, 25mm away from the extra protection plasterboard
В	021	On the top of the 25mm galvanised steel pipe, 25mm away from the sealant
	022	On the side of the 25mm galvanised steel pipe, 25mm away from the sealant
	023	On the top of the sealant cone, 25mm away from the pipe.
	024	On the side of the sealant cone, 25mm away from the pipe.
	025	On the extra protection plasterboard, 25mm away from the sealant
	026	On the extra protection plasterboard, 25mm away from the sealant
	027	On the sealant in the extra protection plasterboard channel, 25mm away from the sealant fillet cone
	028	On the extra protection plasterboard, 25mm away from the wall system below the extra protection plasterboard channel.
	029	On the wall system, 25mm away from the extra protection plasterboard
	030	On the wall system, 25mm away from the extra protection plasterboard
С	031	On the top of 32mm galvanised steel pipe, 25mm away from the sealant
	032	On the side of 32mm galvanised steel pipe, 25mm away from the sealant
	033	On the top of the sealant cone, 25mm away from the galvanised steel pipe
	034	On the side of the sealant cone, 25mm away from the galvanised steel pipe
	035	On the wall system, 25mm away from the top of the sealant cone
	036	On the wall system, 25mm away from the side of the sealant cone
D (west)	041	On the top of the bundle of TPS cables, 25mm away from the sealant
	042	On the side of the bundle of TPS cables, 25mm away from the sealant
	043	On the top of the sealant cone, 25mm away from the bundle of TPS cable
	044	On the side of the sealant cone, 25mm away from the bundle of TPS cable
	045	On the wall system, 25mm away from the top of the sealant cone
	046	On the wall system, 25mm away from the side of the sealant cone
D (East)	051	On the top of the bundle of TPS cables, 25mm away from the sealant
	052	On the side of the bundle of TPS cables, 25mm away from the sealant
	053	On the top of the sealant cone, 25mm away from the bundle of TPS cable
	054	On the side of the sealant cone, 25mm away from the bundle of TPS cable
	055	On the wall system, 25mm away from the top of the sealant cone
	056	On the wall system, 25mm away from the side of the sealant cone







Penetration system	T/C #	Description
Е	101	On the 16mm2 cables, 25mm away from the sealant cone
	102	On the 6mm2 cable, 25mm away from the sealant cone
	103	On the 185mm2 cable, 25mm away from the sealant cone
	104	On the 630mm2 cable, 25mm away from the sealant cone
	105	On the sealant cone, 25mm away from the 16mm2 cables
	106	On the sealant cone, 25mm away from the 630mm2 cable
	107	On the wall system, 25mm away from the top of sealant cone.
	108	On the wall system, 25mm away from the top of sealant cone.
	109	On the 16mm2 cable, 400mm away from the wall system
	110	On the 6mm2 cable, 400mm away from the sealant cone
	111	On the 185mm2 cable, 400mm away from the sealant cone
	112	On the 630mm2 cable, 400mm away from the sealant cone
	113	On the wall system, 25mm away from the bottom of sealant cone.
	114	On the sealant cone, 25mm away from the bottom of cable tray
	115	On the bottom of cable tray, 25mm away from the sealant
	116	On the bottom of cable tray, 400mm away from the wall system
F	121	On the communication cables, 25mm away from the sealant cone
	122	On the sealant cone, 25mm away from the communication cables
	123	On the wall system, 25mm away from the top of sealant cone
	124	On the communication cables, 400mm away from the wall
	125	On the wall system, 25mm away from the bottom of sealant cone
	126	On the sealant cone, 25mm away from the bottom of communication cables.
	127	On the bottom of cable tray, 25mm away from the bottom of sealant cone
	128	On the bottom of cable tray, 400mm away from the wall system







Appendix E Test data

E.1 Furnace temperature and severity




Figure 7: Furnace thermocouple temperature vs time

E.2 Furnace pressure

The furnace pressure was set to 15Pa at the centre of the lowest penetration.

Table 11 Furnace pressure

Time (minutes)	Average pressure (Pa)	Time (minutes)	Average pressure (Pa)	Time (minutes)	Average pressure (Pa)
5-10	54	65-70	17	125-130	15
10-15	23	70-75	15	130-135	16
15-20	16	75-80	16	135-140	16
20-25	16	80-85	17	140-145	17
25-30	16	85-90	17	145-150	15
30-35	18	90-95	17	150-155	18
35-40	17	95-100	16	155-160	15
40-45	16	100-105	16	160-165	18
45-50	17	105-110	15	165-170	16
50-55	17	110-115	15	170-175	15
55-60	18	115-120	17	175-180	16
60-65	19	120-125	17		

Test standard: Sections 2 and 10 of AS 1530.4:2014

Job number: 48763900







E.3 Specimen Temperatures




Figure 15 Penetration system A (around the bundle of cable) – temperature vs time








Figure 16 Penetration system A (on the extra protection board and wall system) – temperature vs time




Figure 17 Penetration system B (near the galvanised steel pipe) – temperature vs time








Figure 18 Penetration system B (on the extra protection board and wall system) – temperature vs time




Figure 19 Penetration system C – temperature vs time








Figure 20 Penetration system D (on the west penetration) – temperature vs time




Figure 21 Penetration system D (on the east penetration) – temperature vs time








Figure 22 Penetration system E (on the cables, 25 mm away from sealant) – temperature vs time




Figure 23 Penetration system E (on the sealant and 25 mm away from sealant) – temperature vs time








Figure 24 Penetration system E (on the cables, 400 mm away from wall system)–
temperature vs time




Figure 25 Penetration system E (TC on the bottom side of the specimen) – temperature vs time








Figure 26 Penetration system F (on the top side) – temperature vs time




Figure 27 Penetration system F (on the bottom side) – temperature vs time







Table 12 Test specimen temperatures

Penetration	T/C	Description ¹		Temp (°	C) at t (minutes)		Limit ²
system	#		t=0	t=60	t=90	t=120	t=180	(minutes)
А	011	On the service	13	52	65	75	101	-
	012	On the service	13	52	66	76	98	-
	013	On the extra protection plasterboard	13	39	51	61	74	-
	014	On the extra protection plasterboard	13	39	50	54	69	-
	015	On the sealant	13	44	61	69	80	-
	016	On the extra protection plasterboard	13	37	47	50	62	-
	017	On the separating element	13	65	72	76	104	-
	018	On the separating element	13	63	71	75	103	-
В	021	On the service	13	74	92	109	143	-
	022	On the service	13	74	93	109	144	
	023	On the sealant cone	13	90	97	105	125	-
	024	On the sealant cone	13	91	106	122	167	-
	025	On the extra protection plasterboard	13	43	55	66	80	-
	026	On the extra protection plasterboard	13	45	56	60	76	-
	027	On the sealant	13	55	69	74	89	-
	028	On the extra protection plasterboard	13	36	46	50	64	-
	029	On the separating element	13	70	74	79	119	-
	030	On the separating element	13	64	71	76	107	-
С	031	On the service	13	108	132	148	270	153
	032	On the service	13	107	131	148	268	155
	033	On the sealant cone	13	87	94	99	143	-
	034	On the sealant cone	13	79	87	92	102	-
	035	On the separating element	13	72	76	87	247	173
	036	On the separating element	13	71	77	86	288	169
D (west)	041	On the service	13	117	150	169	325	137
	042	On the service	13	121	156	174	282	156
	043	On the sealant cone	13	79	85	90	104	-
	044	On the sealant cone	13	76	84	88	102	-
	045	On the separating element	13	74	75	85	280	171
	046	On the separating element	13	73	76	85	323	168
D (east)	051	On the service	13	121	156	188	348	125
	052	On the service	13	101	125	151	266	164
	053	On the sealant cone	13	81	88	93	122	-
	054	On the sealant cone	12	73	83	86	101	-







Penetration	T/C	Description ¹		Temp (°C) at t (minutes)				Limit ²
system	#		t=0	t=60	t=90	t=120	t=180	(minutes)
	055	On the separating element	13	69	73	81	314	167
	056	On the separating element	13	69	73	84	332	166
Е	101	On the 16 mm ² cable	13	100	88	101	198	177
	102	On the 6 mm ² cable	13	81	117	154	242	155
	103	On the 185 mm ² cable	13	133	168	189	341	123
	104	On the 630 mm ² cable	13	196	268	340	489	58
	105	On the sealant cone	13	75	85	86	97	-
	106	On the sealant cone	13	75	87	92	105	-
	107	On the separating element	13	70	76	84	193	179
	108	On the separating element	13	69	75	84	200	178
	109	On the 16 mm ² cable	13	60	83	101	119	-
	110	On the 6 mm ² cable	13	32	43	53	76	-
	111	On the 185 mm ² cable	13	78	118	149	176	-
	112	On the 630 mm ² cable	13	118	153	166	220	157
	113	On the separating element	13	63	70	72	107	-
	114	On the sealant cone	13	67	80	83	92	-
	115	On the bottom of cable tray	13	55	103	150	204	146
	116	On the bottom of cable tray	13	31	42	54	75	-
F	121	On the communication cable	13	97	127	168	383	142
	122	On the sealant cone	13	74	80	84	102	-
	123	On the separating element	13	67	74	80	231	171
	124	On the communication cable	13	43	60	83	100	-
	125	On the separating element	13	64	70	73	113	-
	126	On the sealant cone	13	57	71	76	87	-
	127	On the bottom of cable tray	13	82	135	189	299	122
	128	On the bottom of cable tray	13	38	47	64	98	-

Note:

- ¹ Refer to Table 10 for the locations of thermocouples as only a generic description is included in the table.
- Limit time is the time to the nearest whole minute, rounded down to the nearest minute, at which the temperature recorded by the thermocouple does not rise by more than 180 K above the initial temperature.
- Under limit column indicates the temperature limit was not exceeded during the test period or up until the time of integrity failure if a failure occurred.



West

East





Appendix F Photographs




Figure 28 Unexposed face of the specimen before the start of the test




Figure 29 Exposed face of the specimen before the start of the test









West

East




Figure 30 Unexposed face of the specimen at the end of the test



Figure 31 Exposed face of the specimen at the end of the test





Warringtonfire Australia Pty Ltd ABN 81 050 241 524

Perth

Unit 22, 22 Railway Road Subiaco WA 6008 Australia T: +61 8 9382 3844

Sydney

Suite 802, Level 8, 383 Kent Street Sydney NSW 2000 Australia T: +61 2 9211 4333

Canberra

Unit 10, 71 Leichhardt Street Kingston ACT 2604 Australia T: +61 2 6260 8488

Brisbane

Suite 6, Level 12, 133 Mary Street Brisbane QLD 4000 Australia T: +61 7 3238 1700

Melbourne - NATA accredited laboratory

409-411 Hammond Road Dandenong South VIC 3175 Australia T: +61 3 9767 1000

General conditions of use

The data, methodologies, calculations and results documented in this report specifically relate to the tested specimen/s and must not be used for any other purpose. This report may only be reproduced in full. Extracts or abridgements must not be published without permission from Warringtonfire.

All work and services carried out by Warringtonfire are subject to, and conducted in accordance with, our standard terms and conditions. These are available on request or at https://www.element.com/terms/terms-and-conditions.